

**DLCO-EA AIRCRAFT SITREP AS AT 31<sup>ST</sup> DECEMBER, 2008**

A/C REG.	5Y-BCJ Beaver	5Y-BCK Beaver	5Y-BCL Beaver	5Y-KRD Beaver	5Y-DLA Caravan	5Y-DLO Baron	5Y-BBB Islander	5Y-DLD Turbo Beaver
C OF A DUE DATE	27/3/09	06/01/2010	IN PROGRESS	04/03/09	15/02/09	IN PROGRESS	03/04/09	IN PROGRESS
CHECK III	27/4/2010	07/01/2012	19/01/11	13/8/2010	N/A	IN PROGRESS	27/4/2011	13/01/11
PROP. 3 YR INSP. DATE	11/5/09	17/11/2011	19/12/10	26/03/10	6/08/10	PORT: 12/11/2010 STBD: 5/5/2011	PORT: 6/09/09 STBD: 6/09/09	17/07/2010
A/F HOURS	333:00	1:25	142:35	154:35	2063:00	499:15	166:35	7:40
ENGINE (S) HRS	859:25	308:00	142:35	154:35	3482:00	PORT: 00:00 STBD: 00:00	PORT: 1292:10 STBD: 1292:10	7:40
PROP. HRS	1542:55	1:25	142:35	503:25	965:45	PORT: 1346:25 STBD: 1278:05	PORT: 2107:20 STBD: 2107:20	7:40
LOCATION	UNDER ACCIDENT REPAIR	QUELEA KENYA	STBY NAIROBI	UNDER ACCIDENT REPAIR	UNHCR MWANZA	NAIROBI MAINTENANCE	MWANZA	STBY NAIROBI

**NB**



**IMMEDIATE ATTENTION**



**TO BE NOTED**

**Distribution:** Director  
CA  
OC & CP  
Technical Records  
Aircraft Stores  
Mwanza Field Office

Prepared by:- Technical Records  
Checked by:- Chief Engineer