

DLCO-EA AIRCRAFT SITREP AS AT 31ST MARCH, 2010

A/C REG.	5Y-BCJ Beaver	5Y-BCK Beaver	5Y-BCL Beaver	5Y-KRD Beaver	5Y-DLA Caravan	5Y-DLO Baron	5Y-BBB Islander	5Y-DLD Turbo Beaver
C OF A DUE DATE	27/3/09	10/01/2011	13/04/2011	04/03/09	20/02/2011	IN PROGRESS	13/04/2011	02/03/2011
CHECK III	27/4/2010	07/01/2012	19/01/11	13/8/2010	N/A	IN PROGRESS	27/4/2011	13/01/2011
PROP. 5 YR OVERHAUL		17/11/2013	19/12/2012		06/08/2012		PORT:28/9/2014 STBD:28/9/2014	17/07/2012
A/F HOURS	333:00	139:00	281:15	154:35	306:20	499:15	288:50	24:40
ENGINE (S) HRS	859:25	446:15	281:15	154:35	124:45	PORT: 00:00 STBD: 00:00	PORT: 1410:30 STBD: 1410:30	24:40
PROP. HRS	1542:55	139:00	281:15	503:25	1721:15	PORT: 1346:25 STBD: 1278:05	PORT: 70:20 STBD: 70:20	24:40
LOCATION	UNDER ACCIDENT REPAIR	QUELEA TANZANIA	STBY NAIROBI	UNDER ACCIDENT REPAIR	UNHCR MWANZA	NAIROBI MAINTENANCE	NAIROBI STANDBY	STBY NAIROBI

NB



IMMEDIATE ATTENTION



TO BE NOTED

Distribution: Director
CA
OC & CP
Technical Records
Aircraft Stores
Mwanza Field Office

Prepared by:- Technical Records
Checked by:- Chief Engineer