

DLCO-EA AIRCRAFT SITREP AS AT 30TH JUNE, 2009

A/C REG.	5Y-BCJ Beaver	5Y-BCK Beaver	5Y-BCL Beaver	5Y-KRD Beaver	5Y-DLA Caravan	5Y-DLO Baron	5Y-BBB Islander	5Y-DLD Turbo Beaver
C OF A DUE DATE	27/3/09	06/01/2010	1/03/2010	04/03/09	20/02/2010	IN PROGRESS	08/04/10	21/01/2010
CHECK III	27/4/2010	07/01/2012	19/01/11	13/8/2010	N/A	IN PROGRESS	27/4/2011	13/01/11
PROP. 3 YR INSP. DATE	11/5/09	17/11/2011	19/12/10	26/03/10	6/08/10	PORT: 12/11/10 STBD: 5/5/2011	PORT: 6/09/09 STBD: 6/09/09	17/07/2010
A/F HOURS	333:00	113:05	235:25	154:35	2346:50	499:15	192:15	7:40
ENGINE (S) HRS	859:25	419:40	235:25	154:35	3765:45	PORT: 00:00 STBD: 00:00	PORT: 1325:20 STBD: 1325:20	7:40
PROP. HRS	1542:55	113:05	235:25	503:25	1249:15	PORT: 1346:25 STBD: 1278:05	PORT: 2138:25 STBD: 2138:25	7:40
LOCATION	UNDER ACCIDENT REPAIR	QUELEA KENYA	LOCUST ETHIOPIA	UNDER ACCIDENT REPAIR	UNHCR MWANZA	NAIROBI MAINTENANCE	STBY MWANZA	STBY NAIROBI

NB



IMMEDIATE ATTENTION



TO BE NOTED

Distribution: Director
CA
OC & CP
Technical Records
Aircraft Stores
Mwanza Field Office

Prepared by:- Technical Records
Checked by:- Chief Engineer